





Restoration & Crown




Hybrid Resin



Ceramic Inlay



Remaining adhesive





Marginal Leakage



White light Image





Cement degradation



Cement degradation



Tooth underneath the crown



Cracked Line

